



*Working with Oregonians  
to ensure safe building  
construction while  
supporting a positive  
business climate.*

## **Errata for the 2007 Oregon Structural Specialty Code, first printing**

**Contact:** Richard Rogers, Structural Program Chief, 503-378-4472 or [richard.rogers@state.or.us](mailto:richard.rogers@state.or.us)  
Shane Sumption, Fire, Life-Safety / ADA, 503-378-4635 or [shane.r.sumption@state.or.us](mailto:shane.r.sumption@state.or.us)

---

~~Strikethrough~~ text represents deleted language.

Underlined text represents added language.

---

1. Page 181, Section 903.2.7.2, "**SUBSTANTIAL ALTERATION.**"  
"Any alterations ~~of~~ where the total cost of all alterations... ."
2. Page 436, Section 1802.4.2  
"...geologic hazards as required in Section ~~1802.6.1~~ 1802.7."
3. Page 611, Section 2702.2.5  
"...egress in accordance with Section ~~1007.4~~ 1107."
4. Page 191, Section 907.2.9  
The following note should be added to the end of the section:  
**Note:** Readers should also consult the Oregon smoke detector law located in ORS 479.250 through 479.300.
5. Page 93, Table 601  
Footnote c should be added in the boxes for "Roof construction Including supporting beams and joists" (bottom row of table) under columns: Type II B, Type III A, and Type III B.

