



Oregon

Theodore R. Kulongoski, Governor

Department of Consumer and Business Services

Building Codes Division

1535 Edgewater Street NW

PO Box 14470

Salem, OR 97309-0404

(503) 378-4133

FAX (503) 378-2322

<http://bcd.oregon.gov>

July 20, 2009

AMENDED PUBLIC MEETING NOTICE
Oregon Structural Specialty Code Committee

Building Codes Division
Conference Room A
1535 Edgewater St NW
Salem, OR 97309

July 22, 2009
9:00 a.m. to **5:00** p.m.*

Agenda:

The bold items below have been added from the previous notice and include some previously tabled items as well as items discussed at previous meetings that require ratification.

- Review following substantial model code changes:
 - ✓ **Section 419 Live/Work Units – Chapter 11 correlation**
 - ✓ Section 915 Emergency Radio Responders
 - ✓ Section 1609.6 Alternate Wind Design
 - ✓ Section 1614 High Rise Structural Requirement

- Review following editorial and non substantive model code changes:
 - ✓ Chapter 1 Administration
 - ✓ **Section 408 Group I-3 Occupancies**
 - ✓ **Section 705.2 Projections**
 - ✓ Chapter 18 Soils and Foundations

- Review following existing Oregon amendments:
 - ✓ **EA07-02 Definitions relative to Section 408**
 - ✓ **EA07-04 Section 408**
 - ✓ **EA07-10 Rooms within healthcare**
 - ✓ **EA07-10 Roof access**
 - ✓ **EA07-16 Basic Wind Speeds**
 - ✓ EA07-18 Soils and Foundations
 - ✓ EA07-21 Masonry
 - ✓ EA07-23 Wood
 - ✓ EA07-29 through EA07-32
 - ✓ EA07-34 through EA07-48

- Review following new amendments public code change proposals:
 - ✓ OSSC10-03 Fire Proofing
 - ✓ OSSC10-04 Fall Protection
 - ✓ OSSC10-30 through OSSC10-34 Chapter 34 Existing Buildings
 - ✓ OSSC10-35 Table 601 Non-bearing Wall Fire Rating
 - ✓ OSSC10-42 Chapter 34 Existing Buildings
 - ✓ OSSC10-43 Chapter 11 Accessible Handrails
 - ✓ OSSC10-45 BCD requests reconsideration dealing with Public Restrooms

- Review following New BCD amendment proposals:
 - ✓ OSSC10-47 Fuel Storage Requirements for Emergency Generators
 - ✓ OSSC10-48 915, Emergency Responder Radio Coverage
 - ✓ OSSC10-49 Chapter 11 Handrail Coordination with Chapter 10

- Review Existing Statewide Alternate Methods

- Review Existing Statewide Interpretations

- Discussion of Possible **Fiscal Impact**

* The meeting has been extended to allow for the possibility of completing the committee's work without scheduling of additional meetings.

Code proposals can be found at: <http://www.bcd.oregon.gov/committees/10ossc/proposals.html>

Video-recorded live meetings and further committee information can be viewed on the Oregon Structural Specialty Code Review Committee webpage at <http://www.bcd.oregon.gov/committees/10ossc.html>.

For more information, please contact Richard Rogers at 503-378-4472 or Richard.Rogers@state.or.us.

**Auxiliary aids for people with disabilities are available upon advance request.
Vehicles with “E” plates should not park in customer only spaces.**