

**Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04**

2003-0572

Boiler/Pressure \$3,000.00

Respondent:

Industrial Steel & Supply Co., Inc.

Frank Searfus

North Bend

OR

Complaint Source: Mike Graham BCD Boiler Inspector

Final Action: Consent Order

Compliance Achieved: Yes

Type of Violator: 1st time violator

Alleged Violations:

On or about the period of April through December 2002, at 3959 Sheridan Avenue, North Bend, Oregon, the Respondent installed a Western Pressure Vessel, NB# 55, for the account of another, without first having obtained a valid pressure vessel installation permit, in violation of ORS 480.630(6).

/

On or about the period of April through December 2002, at 3959 Sheridan Avenue, North Bend, Oregon, Respondent installed a Western Pressure Vessel, NB# 57, for the account of another, without first having obtained a valid pressure vessel installation permit, in violation of ORS 480.630(6).

/

On or about the period of April through December 2002, at 3959 Sheridan Avenue, North Bend, Oregon, Respondent engaged in the business of installing two Western Pressure Vessels, NB# 55 & NB# 57, for the account of another, without having a valid Oregon Boiler/ Pressure Vessel Business license, in violation of ORS 480.630(1).

/

On or about January 17, 2003, installation and operating permits for the pressure vessels, NB# 55 & NB# 57, were issued by the Division, and all necessary inspections were performed and installations approved.

/

Other Comments:

Respondent admitted the violation occurred and agreed to the entry of a Consent Order

Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04

acknowledging a commitment to comply with the Oregon Specialty Codes. Compliance has been achieved in the matter. The Respondent was assessed a \$3,000.00 civil penalty. The Respondent will pay \$2,250.00, and the \$750.00 balance of the civil penalty will be stayed for a period of three years. The stayed civil penalty will be discharged at the end of the three-year period, provided there are no subsequent violations during the three-year period.

Case was received by the Division on July 24, 2003.

End

**Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04**

2003-0807

Boiler/Pressure \$3,000.00

Respondent:

Radabaugh Corporation
Ronald Radabaugh
Bend

OR

Complaint Source: Jerry Klug Building Codes Division

Final Action: Consent Order

Compliance Achieved: Yes

Type of Violator: 1st time violator

Alleged Violations:

On or about the period of July through September 2003, at 19800 S.W. Touchmark Way, Bend, Oregon, Respondent installed a Ray Pak Snow Melt Boiler, N.B. #210726, for the account of another, without first having obtained a valid boiler installation permit, in violation of ORS 480.630(6).

On or about the period of July through September 2003, at 19800 S.W. Touchmark Way, Bend, Oregon, Respondent installed a Ray Pak Snow Melt Boiler, N.B. #210727, for the account of another, without first having obtained a valid boiler installation permit, in violation of ORS 480.630(6).

On or about the period of July through September 2003, at 19800 S.W. Touchmark Way, Bend, Oregon, Respondent engaged in the business of installing a Ray Pak Snow Melt Boiler, N.B. #210727, and a Ray Pak Snow Melt Boiler, N.B. #210726, for the account of another, without having a valid Oregon Boiler/Pressure Vessel Business License, in violation ORS 480.630(1).

On or about November 4, 2003, at 19800 S.W. Touchmark Way, Bend, Oregon, Respondent placed into operation a Ray Pak Snow Melt Boiler, N.B. #210727, for which a valid permit had not been issued, in violation of ORS 480.585(3).

On or about November 7, 2003, boiler installation permits, #24540 and #24539, were issued by the Division for the installation and operation of the boilers previously identified in this order, after inspection and approval.

On or about November 10, 2003, a valid Oregon Boiler/Pressure Vessel Business license was issued to the Respondent.

Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04

Other Comments:

Respondent admitted the violation occurred and agreed to the entry of a Consent Order acknowledging a commitment to comply with the Oregon Specialty Codes. Compliance has been achieved in the matter. The Respondent was assessed a \$3,000.00 civil penalty. The Respondent will pay \$1,500.00, and the \$1,500.00 balance of the civil penalty will be stayed for a period of three years. The stayed civil penalty will be discharged at the end of the three-year period, provided there are no subsequent violations during the three-year period.

Respondent had allowed their boiler contractor's license to expire prior the the time the installtions were made. Respondent has obtained a new contractor's license with the division.

Case was received by the Division on November 13, 2003.

End

**Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04**

2003-0571

Boiler/Pressure \$2,000.00

Respondent:

Gary McInnis
Yakima

WA

Complaint Source: Thomas League Building Codes Division

Final Action: Consent Order

Compliance Achieved: Yes

Type of Violator: 1st time violator

Alleged Violations:

On or before May 5, 2003, at 34075 East Walls Road, Hermiston, Oregon, Respondent engaged in the business of installing a Roy Hanson pressure vessel, National Board number 179750, for the account of River Gate Farms, without a valid Oregon Boiler/Pressure Vessel Business license, in violation of ORS 480.630(1).

On or before May 5, 2003, at 34075 East Walls Road, Hermiston, Oregon, Respondent engaged in the business of installing a Roy Hanson pressure vessel, National Board number 179750, for the account of River Gate Farms, without first having obtained a valid installation permit, in violation of ORS 480.630(6).

Respondent later obtained a valid Oregon Boiler/Pressure Vessel Business license and then secured an installation permit on February 11, 2004. The installation was performed by a licensed individual.

Other Comments:

By signing the Consent Order, Respondent has committed to future compliance. Respondent was assessed a total civil penalty of \$2,000. Respondent will pay \$1,250 of the civil penalty and the balance will be stayed for a period of three years according to the terms of the order.

End

**Building Codes Division
Board of Boiler Rules Compliance Report
Compliance Actions
As of 5/25/04**

2004-0034

Boiler/Pressure \$1,000.00

Respondent:

Pacific Sales & Service Inc.
Bart Dahlstrom
Troutdale

OR

Complaint Source: Clayton Rhodes Building Codes Division

Final Action: Consent Order

Compliance Achieved: Yes

Type of Violator: 1st time violator

Alleged Violations:

On or about November 19, 2003, at 301 S Redwood Street, Canby, Oregon, Respondent employed Randy Burns, who did not hold any valid Oregon Boiler/Pressure Vessel Certification, to install a Dressler pressure vessel, National Board Number 27569, for the account of another, in violation of ORS 480.632.

An installation permit was obtained by the company; however, the employee who made the installation was not the employee listed on the permit.

Other Comments:

By signing the Consent Order, Respondent has committed to future compliance. Respondent was assessed a \$1,000 civil penalty. Respondent will pay the entire \$1,000 civil penalty.

End