

Board of Boiler Rules for June 2, 2009

| Summary report - Cases previously resolved by division | | | | | | | | |
|---|--|---|------------------------------|--------------------------|--------------------|-------------------------|-----------------------|---|
| Case # | Name | Violation | Location of violation | Date of violation | Matrix code | Penalty assessed | Penalty to pay | Other comments |
| 2009-0021 Paul | Reyco Systems, Inc., an unlicensed contractor | Installed a steam potato peeler pressure vessel <ul style="list-style-type: none"> • No boiler contractor's license • Allowed an unlicensed person to install a pressure vessel • No valid pressure vessel installation permits | Boardman | December 2008 | New Matrix | \$5,500 | \$3,500 | Consent Order. Complaint submitted by BCD inspector. |
| 2008-0121 Paul | Rite-Way Heating & Air Conditioning Inc., a licensed limited maintenance specialty contractor HVAC/R and restricted energy contractor | Installed a hot-water-heating boiler <ul style="list-style-type: none"> • No boiler contractor's license • Allowed an unlicensed person to install a boiler • No valid boiler installation permits | Hillsboro | January 2008 | New Matrix | \$5,500 | \$5,500 | Default Order. Complaint submitted by BCD inspector. |